COPY BUILDING SAFETY CERTIFICATE

ਦੁਕਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉੰਜਾਰੀ ਉਪ ਮੰਡਲ ਨੈ. 2, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ ਈ-ਮੇਲ :- sdecd2pwdmlk@gmail.com

ਵੱਲ

Principal,

Sant Attar Singh Akal Academy, Village Bhojowall, Distt. Sangrur.

ਨੇਬਰ 155

BIST: 07-06-2023

হিদা:-

ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਮੋਡਣੀ ਸਰਣੀਫਿਪੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

SANT ATTAR SINGH AKAL ACADEMY BHOJOWALI (DISTT. SANGRUR)

ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ ਨਿੱਲ ਮਿਤੀ 08-05-2023

ਉਪਰੇਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦੇ ਸਹਾਇਕ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਬਿਲਡਿੰਗ ਦਾ ਨਿਹੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2023-24 (31.03.2024) ਤੱਕ ਬਾਹਰੇ ਵੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿਚ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ਨਲ ਆਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨਟੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੇ ਚੈਕ ਕਰਵਾਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ ਜੇਕਰ ਹੜ੍ਹ, ਬੁਦਰਤੀ ਆਫਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਂਹਾ ਬਹਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨਟੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੇ ਚੈਕ ਕਰਵਾਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ । ਇਸ ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਇਸ ਦਫ਼ਤਰ ਦੀ ਜੀ.ਆਰ ਨੈ: 665438 ਮਿਤੀ 08-06-2023 ਅਤੇ ਚਲਾਨ ਨੈ: CPACUWMD23 ਰਾਹੀਂ 10,000/- ਰੂਪਏ ਜਮਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ । ਸਕੂਲ ਦੇ ਫਾਇਰ ਸੋਫਟੀ ਸਰਟੀਫਿਕੇਟ ਨੂੰ 19 ਜੁਲਾਈ 2023 ਤੋਂ ਬਾਅਦ ਚੀਨਿਊ ਕਰਵਾ ਕੇ ਇਸ ਦਫ਼ਤਰ ਵਿੱਚ ਜਮ੍ਹਾਂ ਕਰਵਾਇਆ ਜਾਵੇ, ਅਜਿਹਾ ਨਾ ਕਰਨ ਦੀ ਸੁਰਤ ਵਿੱਚ ਆਪ ਦੇ ਸਕੂਲ ਦਾ ਸੋਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 19 ਜੁਲਾਈ 2023 ਤੋਂ ਬਾਅਦ ਚੰਦ ਸਮਝਿਆ ਜਾਵੇਗਾ।

ਇਸ ਤੋਂ ਇਲਾਵਾ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਸਰਕਾਰ ਦੀਆਂ ਹੁੰਦਾਇਤਾ ਅਨੁਸਾਰ ਸਕੂਲ ਵੱਲੋਂ ਸਤਕ ਤੋਂ ਅਪਰੇਚ ਲੈਣ ਸਬੰਧੀ ਐੱਨ.ਓ.ਸੀ. ਲਿਆ ਜਾਣਾ ਲੋੜੀਂਦਾ ਹੈ, ਇਸ ਸਬੰਧੀ ਵੱਖਰਾ ਕੇਸ ਮੰਡਲ ਦਫਤਰ ਪਾਸ ਜਮ੍ਹਾ ਕਰਵਾਇਆਂ ਜਾਵੇ ਜੇਕਰ ਆਪ ਵੱਲੋਂ ਐੱਨ.ਓ.ਸੀ ਨਹੀਂ ਲਿਆ ਜਾਂਦਾ ਤਾਂ ਅਗਲੇ ਸਾਲ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਨਹੀਂ ਕੀਤਾ ਜਾਵੇਗਾ।

ਨੱਥੀ/ਸੇਫਟੀ ਰਿਪੋਰਟ

ਉਪ ਸੰਡਲ ਇਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੇਟਲਾਨ੍ਨੇ

ਪਿੱਠ ਔਕਣ ਨੂੰ:

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸਾਖਾ, ਮਾਲੇਰਕੈਟਲਾ ਜੀ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਦਫ਼ਤਰੀ ਪੱਤਰ ਨੰ:1371-73 ਮਿਤੀ 06-06-2023 ਦੇ ਦਿੱਤੇ ਦਿਸ਼ਾ-ਨਿਰਦੇਸ਼ ਅਨੁਸਾਰ ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਹੈ ਅਤੇ ਇਹ ਆਪ ਜੀ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

> ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਹੀ ਉਪ ਮੰਡਲ ਨੈਂ:2 ਭ ਤੇ ਮ ਸ਼ਾਅ, ਮਾਲੇਰਕੋਟਲਾ।

HON ARMEN

Cant Star Singh Akal Academs

Sant Attar Singh Akal Academy BHOJOWALI (Distt. Sangrur) C.B.S.E.AM. Ro. 1630695

Building Safety Report

Name of School: - SANT ATTAR SINGH AKAL ACADEMY BHOJOWALI (DISTT. SANGRUR)

As per report of Sh. Harcharan Singh Assistant Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:

- The Parameters to check the stability and safety of building such as Structural Design, Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
- In case any addition, alteration, expansion and modification to this building are required/to be done, regarding this, inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
- In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
- A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- 5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
- The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
- This report is for the covered area of the school building 20471.00 Sft which is submitted by the owner of the school building as per drawing.
- 8. The building of the school is constructed as framed structure/brick masonry.
- 9. This report is not valid for legal purpose.
- 10. That the fee charges for the year 2023-2024 is 10,000/-

As per visually inspection as reported by the concerned Assistant Engineer the above building may be used for normal use for One year up to 31-3-2024 subject to the above conditions.

Sub-Divisional Engineer, Const. Sub-Division No2. PWD B&R Malerkotla.

Shajowali (Disti Sangrun

Sant Attar Singh Akal Academy BHOJOWALI (Distt. Sangrur) C.B.S.E.ASI.No.1630695